



STAMP Tag Deploying Form

1.	Tagged by: _Mary Beth & Dave	
2.	Tag Number(s) (####):_Test Tag 0000b	
3.	Date: _June 8, 2023 Time : _	10:40am pm
	Tide level: High Medium Lo	w N/A
4.	Name of wreck (if known):N/A	
5.	Description: How did the wreckage reach its	present position?
	Float Uncovered X Other Was brough	ght to Nature Center at
	Assateague State Park	
6.	Main Material of Construction: What is the wreckage material?	Skip the following questions if not wooden wreckage
	X Wood ☐ Steel ☐ Iron ☐ Fiberglass ☐	If the wreckage is wood, does it appear to be:
	Check the following boxes if these details are present on the wreckage:	☐ Hand hewn x Machine Cut☐ Both☐ Other
	X Treenails	Look at the images on the
	Round Spikes Other	instruction sheet and give your best guess on what part of the
	Check the following boxes if the materials are present on the wreckage:	shipwreck you believe you foundFloor timber?
	X Wood x Iron □ Copper □ Steel	
	☐ Iron concretion & staining	

	Deterioration: What does the level of deterioration seem to be? ☐ No deterioration x Partially deteriorated ☐ Heavily deteriorated Exposure: Check the best choice for how exposed the wreckage is: x Completely exposed ☐ Partially exposed ☐ Nearly covered
9.	Directions: Adjacent to the Nature Center along the trail to the beach at Assateague
	State Park
10	Estimated distance from the high tide line:
	☐ below(ft) x above_20(ft)
	beach zone x behind primary dune
	Latitude:38° 18' 40" N Longitude:75° 8' 30" W Length/Width/Thickness of timber: Length: _4' 6" Width: _8.5" _Thickness: _7" _Orientation: _redeposited Diameter of wooden fasteners: 1" Distance between 2 fasteners: 8 treenails present in zigzag pattern with distances of 5.5", 8.5", 5", 6.5", 5", 6", 6", 5.5" Pictures: _None submitted (Name/Id#)
	(continue on back) .Comments:_Teredo navalis(shipworm) damage, Staining from an iron concretion that is lying beside the timber, some evidence of burning
	Please send this completed form to susan.langley@maryland.gov with photos. Scans of the form or legible photos are acceptable or mail to: Dr. S. Langley, Maryland Historical Trust, 100 Community Place,

Crownsville, MD 21032.